



**2008 Long Range Facility Plan
Conroe Independent School District**

**CAMPUS IMPROVEMENTS -
ADMINISTRATIVE PRIORITIES**

Budget Estimate for:

OAK RIDGE ELEMENTARY

Feeder Zone:

Oak Ridge

NO.	ADMIN. PRIORITY	DESCRIPTION
1		Replace VCT floors with glazed tile pavers in all corridors
2		Update carpet in classrooms per CISD standard (approx: 45 rooms)
3		Repaint exterior HM door and window system at cafeteria
4		Paint sill and CMU base at gym facing bus loop [Repaint of whole bldg estimated]
5		Repaint corridor wall from cafeteria to gym
6		Repaint stage area
7		Repaint all steel lintels at exterior
8		Ceramic tiles in front entry are very slick.
9		Back lot needs repair; potholes on entry road.



**2008 Long Range Facility Plan
Conroe Independent School District**

**CAMPUS IMPROVEMENTS -
ADMINISTRATIVE PRIORITIES**

Budget Estimate for:

OAK RIDGE ELEMENTARY

Feeder Zone:

Oak Ridge

10		Classrooms need to be painted.
11		Bad erosion on playground.
12		Playground space is covered with tree roots and erosion is causing metal culverts and cement to be exposed on the playground.
13		Plexiglass windows need to be replaced with glass on west side of building.
14		Need exterior lighting around perimeter of building
15		Speakers needed on exterior of building.
16		Replace plexiglass at window system at corridor near kitchen
17		Add double doors for security.
18		Revise Admin area configuration for security.
19		Need additional lighting in restroom at room A-10C
20		Replace chalkboards with marker/tack boards (approx: 35 rooms)



**2008 Long Range Facility Plan
Conroe Independent School District**

**CAMPUS IMPROVEMENTS -
ADMINISTRATIVE PRIORITIES**

Budget Estimate for:

Feeder Zone:

OAK RIDGE ELEMENTARY
Oak Ridge

21		Replace HM Door / Window system with Aluminum storefront at all locations near student restroom pods
22		Teacher restroom is desperately needed in the north side of the building.
23		Adult restrooms in the southeast corner of building need to be brought up to code, are in very poor condition. (Re-do Finish)
24		Wall outlets are inadequate for today's needs, circuits continually blow in the building with not much load.
25		Replace lights in unisex and clinic restrooms (always dark).
26		Need better lighting in the bookroom.
27		Emergency lighting needed in or near rooms with no window access (music rooms, 8, 6, 103, 106, 305, 303, 205, 207).
28		Classrooms do not have adequate storage (or currently have makeshift storage). (Add 1 wall of storage casework at 8 (only classrooms)
29		Need coat hooks in every classrooms for coats and backpacks. [Eight classrooms identified by C&I as each needing one entire wall of casework and "cubbies"]
30		Oak Ridge Elem / Stage - Sound - sound has not been installed